

## Compatible Products for Nuclias Unity Solution



| Core Switches  | HW Ver.   | Minimum FW   |
|--|---|--|
| <ul style="list-style-type: none"> <li>DXS-3410-32XY/32SY<sup>2</sup></li> <li>DXS-3610-54S/54T<sup>2</sup></li> <li>DGS-3630-28PC/28SC/28TC/52TC/52PC<sup>1,2</sup></li> </ul>  | <p>Ax</p> <p>Ax</p> <p>Ax</p>   | <p>v1.00.023 or latest</p> <p>v1.01.023 or latest</p> <p>Coming Soon</p>   |
| Aggregation Switches   | HW Ver.   | Minimum FW   |
| <ul style="list-style-type: none"> <li>DXS-3130-28/28P/32S</li> <li>DMS-3130-30TS/30PS</li> <li>DGS-3130-30S/30PS/30TS/54PS/54S/54TS</li> </ul>  | <p>Ax</p> <p>Ax</p> <p>Bx</p>   | <p>v1.31.001 or latest</p> <p>v1.31.001 or latest</p> <p>v2.04.001 or latest</p>   |
| Stackable Smart Switches   | HW Ver.   | Minimum FW   |
| <ul style="list-style-type: none"> <li>DGS-1510-20/28X/28XMP/28/28P/52/52X /52XMP<sup>1,2</sup></li> <li>DGS-1520-28/28MP/52/52MP<sup>1,2</sup></li> <li>DGS-1530-10/20/28/28P/52/52P/28S/28SC<sup>1,2</sup></li> </ul>  | <p>Ax</p> <p>Ax</p> <p>Ax</p>   | <p>Coming Soon</p> <p>Coming Soon</p> <p>Coming Soon</p>   |
| Standard Smart Switches  | HW Ver.   | Minimum FW   |
| <ul style="list-style-type: none"> <li>DXS-1210-10TS/10MP/12SC/12TC/16TC</li> <li>DXS-1250-12/12P/12S/28/28P/28S</li> <li>DXS-1250-28YP</li> <li>DMS-1250-10S/10SP/10SPL/12/12TP/18/18P/28/28P</li> <li>DGS-1210-10/10MP/10P/20/26/28/28MP/28P/52/52MP*</li> <li>DGS-1250-28X/28XMP/52X/52XMP<sup>2</sup></li> <li>DGS-1250-28X/28XP/52X/52XP</li> </ul> | <p>Bx</p> <p>Bx</p> <p>Ax</p> <p>Ax</p> <p>Fx</p> <p>Ax</p> <p>Bx</p> | <p>v2.11.001 or latest</p> <p>Coming Soon</p> <p>v1.01.001 or latest</p> <p>v1.03.013 or latest</p> <p>v6.33.003 or latest</p> <p>v2.10.005 or latest</p> <p>v1.00.010 or latest</p> |
| Easy Smart Switches  | HW Ver.   | Minimum FW   |
| <ul style="list-style-type: none"> <li>DXS-1100-10/10P/10TP<sup>1</sup></li> <li>DGS-1100-16V2/18PV2/24PV2/24V2/26MPV2</li> </ul>  | <p>Bx</p> <p>Ax</p>   | <p>Coming Soon</p> <p>v4.00.30 or latest</p>   |
| Access Point MODEL   | HW Ver.   | Minimum FW   |
| <p>Wi-Fi 7</p> <ul style="list-style-type: none"> <li>DAP-E9560</li> </ul> <p>Wi-Fi 6</p> <ul style="list-style-type: none"> <li>DAP-X3060OU</li> <li>DAP-X3060W</li> <li>DAP-X3060</li> </ul>   | <p>Ax</p> <p>Ax</p> <p>Ax</p> <p>Ax</p>                               | <p>v1.01r028 or latest</p> <p>v1.10r016 or latest</p> <p>v1.10r012 or latest</p> <p>v1.10r025 or latest</p>  |

Note:

1. Indicates upcoming support. The actual availability schedule will follow D-Link's official announcements.

2. **Unity Proxy** installation is required in order to manage devices via the Nuclias Unity Portal.

Please update the device to the Unity-compatible required version to ensure it can be properly managed.

\* If your DGS-1210-10 FX Series firmware version is lower than v6.30.16, please update to this version before upgrading to v6.33.003