# **D-Link**Quick Installation Guide

This product can be used with the following operating systems: Windows XP, 2000



**DPH-50U**VoIP USB Phone Adapter

### **Before You Begin**

You must have at least the following:

- Windows XP/2000
- Pentium 400MHz or Higher
- One Available USB Port
- 128MB RAM
- 10MB Available Hard Disk Space
- CD-ROM Driver

## **Check Your Package Contents**

These are the items included with your purchase :

If any of the above items are missing, please contact your reseller.



DPH-50U VoIP USB Phone Adapter



 CD-ROM (containing Manual and Installation program)



USB 2.0 Cable




• RJ-11 Telephone Cable



## Connecting DPH-50U to your PC



Do not connect the DPH-50U to your computer until instructed to do so by the DPH-50U installation wizard



## Installing the Skype™


If Skype<sup>™</sup> is not already installed on your computer, visit <a href="http://www.skype.com">http://www.skype.com</a> and follow the instructions there to install Skype<sup>™</sup>. Verify that Skype<sup>™</sup> is working before installing the DPH-50U adapter.



## Installing the DPH-50U Driver


#### STEP 1.

Insert the supplied CD-ROM into your PC CD-ROM drive. The installation should start automatically. Please press "Install Utility"




#### STEP 2.

You will see the following popup. Press Yes to proceed or No to cancel.



#### STEP 3.

You will see the End User License Agreement. Click the "I have read ..." checkbox and press the *I Agree* button as shown below.



#### STEP 4.

You will see the following progress bar below indicating that the installation is proceeding.



#### STEP 5.

Wait until you see the following popup and press the OK button.



#### STEP 6.

Connect the USB cable to the DPH-50U adapter USB port as shown below:



#### STEP 8.


You will see the following Windows New Hardware Found Wizard.



Select Install the software automatically (Recommended) and press the **Next** button.


#### STEP 9.

The installation will continue and you will see the following screen.



#### STEP 7.

The other end of the USB cable must be connected to a USB port on your computer as shown below, or to an AC Powered USB hub.






#### **STEP 10.**

When you see the following screen, press the **Finish** button.



#### **STEP 11.**


Then you will see the following Windows New Hardware Found Wizard screen.



Select *Install the software automatically* (Recommended) and press the **Next** button.

#### **STEP 13.**

When you see the following screen, press the **Continue Anyway** button.




#### **STEP 15.**

When you will see the following screen, select the option, "allow this program to use Skype" and press the **OK** button.


#### **STEP 12.**

The installation will continue and you will see the following screen.



#### **STEP 14.**

When you see the following screen, press the **Finish** button.





## **Technical Support**

You can find software updates and user documentation on the D-Link websites.

D-Link provides free technical support for customers within Canada, the United Kingdom, and Ireland.

Customers can contact D-Link technical support through our websites, or by phone.

## For Customers within The United Kingdom & Ireland:

#### D-Link UK & Ireland Technical Support over the Telephone:

08456 12 0003 (United Kingdom)

+44 8456 12 0003 (Ireland)

Lines Open

8.00am-10.00pm Mon-Fri

10.00am-7.00pm Sat & Sun

#### D-Link UK & Ireland Technical Support over the Internet:

http://www.dlink.co.uk ftp://ftp.dlink.co.uk

#### For Customers within Canada:

#### D-Link Canada Technical Support over the Telephone:

1-800-361-5265 (Canada)

Mon. to Fri. 7:30AM to 9:00PM EST

#### D-Link Canada Technical Support over the Internet:

http://support.dlink.ca email: support@dlink.ca

